




Road surface

Eroded bank



Downstream end of 5' diameter culvert on Poplett Hollow Road (west of Route 29)

April - June, 2013  
Storm Damage  
Images, Page 1 of 4